Maryland Historical Trust

Wan y and I kistor tear a	
Maryland Inventory of Historic Properties number: Name:	305) 305(20m
The bridge referenced herein was inventoried by the Maryland S Historic Bridge Inventory, and SHA provided the Trust with elig The Trust accepted the Historic Bridge Inventory on April 3, 20 determination of eligibility.	gibility determinations in February 2001.
MARYLAND HISTORICA	L TRUST
Eligibility Recommended	Eligibility Not RecommendedX
Criteria:ABCD Considerations:A	BCDEFGNone
Comments:	
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001
Reviewer, NR Program: Peter E. Kurtze	Date:3 April 2001

- who

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. M 40 over Broad Run

<u>Location:</u> Street/Road Name and Number: <u>River Road over Broad Run</u>
City/Town: Rockville Vicinity
County: Montgomery
Ownership:State_X_CountyMunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: X yes no
NR listed districtNR determined eligible district locally designatedother Name of District_Chesapeake and Ohio Canal Historic Park_
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X Metal Girder X Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased
Metal Suspension
Metal Arch

_Metal C	antilever
_Concret	re e
_	Concrete Arch _Concrete Slab_Concrete Beam
_	Rigid Frame
	Other Type Name

Description:

Describe Setting:

Bridge No. M 40 carries River Road east-west over Broad Run in Montgomery County, Maryland. The west approach is straight and level, and the east approach is straight but ascends towards the bridge. The approaches appear to be composed of a gravel or macadam wearing surface. The area around the bridge is rural and heavily wooded.

Describe Superstructure and Substructure:

Bridge No. M 40, built in 1911, is a single span 29' long structure with a concrete deck on steel stringers. The deck is a reinforced concrete slab with a macadam wearing surface, and a width of 13'. The superstructure consists of five stringers, two exterior channels and three interior I-beams. The substructure consists of 2 concrete abutments appear to be in fair condition.

A plain concrete apron has been poured in front of Abutment No. 1 in the stream channel to prevent further deterioration of the abutment. Grouted stone rip-rope slope protection around the abutments appears in good condition.

Discuss Major Alterations:

This bridge was rehabilitated in 1976. Further rehabilitation occurred in 1992. During the 1992 rehabilitation, the concrete deck was replaced with a galvanized corrugated steel deck, filled with a bituminous wearing surface. The abutments were cleaned and coated with an epoxy sealant. The 1995 Bridge Inspection Report indicates that three of the steel stringers are steel I-Beams, while the other two are wide flange steel beams.

History:

When Built: 1911 (rehabilitated 1976 and 1992)

Why Built: Local transportation needs

Who Built: Unknown

Why Altered: Structural and safety needs

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

__A Events __Person

__C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

It is unknown whether this bridge was constructed in response to significant events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether the construction and/or alteration of this bridge has had significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

This bridge is already located in an area which is eligible for historic designation. This bridge does not add to the historic and visual character of the district.

Is the bridge a significant example of its type?

This bridge is not a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

No, this bridge does not appear to have retained the integrity of its primary character defining elements as defined within the Context Addendum. This bridge underwent an undocumented rehabilitation in 1976. In 1992 the bridge underwent another rehabilitation. During the 1992 rehabilitation, the concrete deck was replaced with a galvanized corrugated steel deck, filled with a bituminous wearing surface. The abutments were cleaned and coated with an epoxy sealant. The 1995 Bridge Inspection Report indicates that three of the steel stringers are steel I-Beams, while the other two are wide flange steel beams. This indicates that the exterior fascia channels were replaced with I-Beams. The reconstruction may have utilized some of the I-beams from the old bridge, which were then replaced with two new wide flange steel beams.

Should this bridge be given further study before significance analysis is made and Why?

Further research of this bridge is unnecessary. This bridge does not retain its integrity as defined by the Context Addendum, and is not eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Montgomery County

v.d. County Bridge Inspection Files.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.


United States Geological Survey

1968 7.5' Sterling Quadrangle, photorevised 1984.

Surveyor:

Name: Jason D. Moser Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213 Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory	#	M:	16	ğur.	100 miles	State of the last
_						

Name M40-RIVERBOOVER BROAD RUN
County/State MONTGOMERY / MD
Name of Photographer FRANK JULIANO
Date 2 45
Location of Negative SHA
Description ELEVATION SOUTH
Number 24 of 36



Inventory # M: 16-30

Name M40- RIVER ROOVER BROAD RUN
County/State MONTGOMERY / MD
Name of Photographer FRANK JULIANO
Date 2 95
·
Location of Negative SHR
Description Approach East
2 4
Number 35 of 36



Inventory # M: 16-30

Name M40-RIVER RO OVER BROADRUN
County/State MONTGOMERY MO
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHA
Location of regarde
Description ELEVATION NORTH
Number 36 of 34



Inventory # M: 16-30

Name M40-RIVER ROOVER BROAD RUN
County/State MONTGOMERY MO
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHA
Description WEST APPROACH
Number <u>37 of 4</u>